
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: 9/22/2009
Test to be performed:  Smoke Dyed Water X		Supervisor: <u>JAW</u>
Manhole_ID: S08G001MH	Test ID: <u>D1032-006002</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S08G001MH
0			Water Level	
10.10000038			Dye Test Visible	DYE SEEN AT JOINT
14.30000019			Dye Test Visible	DYE SEEN AT JOINT
23.29999924			Dye Test Visible	DYE SEEN AT JOINT
53.59999847			Dye Test Visible	DTE SEEN AT JOINT
68.40000153			Abandoned Survey	DYE TEST IS COMPLETE